SPECIFICATIONS FINISHED FLOORS

pedestal @70A

6060

culture } movement

Living/Dining

Wall Finish Painted in Acrylic Emulsion

Flooring Vitrified Tiles

Bedrooms

Wall Finish Painted in Acrylic Emulsion

Flooring Vitrified tiles or laminated wooden flooring

Bathrooms

Flooring Ceramic tiles

Dado Select ceramic tiles

Fixtures & fittings Granite/marble counter, white sanitary ware and contemporary chrome plated fittings

Kitchen

Flooring Vitrified tiles

Dado Ceramic tiles upto 2' above working platform and the rest painted in oil bound distemper

Platform Granite counter with Single bowl stainless steel sink and drain board

Doors & windows

Windows UPVC

Doors Seasoned hardwood door frames with skin moulded shutters

Facilities

Electrical Electrical copper wiring in concealed conduits for all light and power points

Power Back - up Minimum back-up capabilities: 2BHK - 5 KVA, 3 BHK - 7.5 KVA, 4 BHK - 10 KVA

Air - Conditioning Split air-conditioners in living/dining area & bedrooms

External Spaces Landscaped green areas

Barbeque pit/gazebos for social events

Comfortable seating areas, adequate street lighting and open area lighting

Facade Aesthetically designed external facade made up of a combination of texture paint

and stone cladding/GRC Jaali

Club Exquisite recreational club spread over 2 acres with outdoor and kids' pool, jogging tracks, space for outdoor activities, gymnasium, multi-cuisine restaurants, business centre, banquet hall, state- of-the-art theatre, sports

facilities for table tennis, badminton, squash, pool/billiards, and a high-end spa.