# M3M Escala, Sector 70A, Gurgaon, Group Housing



# **Tentative Specifications & Finishes**

#### **Bedroom**

Walls: Plastic Emulsion with Roller Finish
Floors: Laminated wooden flooring
Doors: Hard Wood Door Frame with Flush Shutter
Windows: UPVC/ Powder coated or Anodized Aluminium Glazing
Ceiling: Plastic Emulsion

## Living/Dining Room

Walls: Plastic Emulsion with Roller Finish
Floors: Vitrified Tiles
Doors: Hard Wood Door Frame with Flush Shutter
Windows: UPVC/ Powder coated or Anodized Aluminium Glazing
Ceiling: Plastic Emulsion

### Kitchen

Walls: 2' high ceramic tiles above counter,balance painted
Floors: Anti skid Ceramic tiles
Doors: Hard Wood Door Frame with Flush Shutter
Windows: UPVC/ Powder coated or Anodized Aluminium Glazing
Ceilings: Oil Bound Distemper Paint
Others: Polished Granite counter with SS sink and CP fittings

#### Toilets

Walls: 7' high dado with ceramic tiles, rest painted
Floors: Anti skid Ceramic tiles
Doors: Hard Wood Door Frame with Flush Shutter
Windows: UPVC/ Powder coated or Anodized Aluminium Glazing
Ceilings: Oil Bound Distemper Paint
Others: Granite marble counter with white sanitary fixtures and CP fittings

### Lift Lobbies

Walls: Selected stone cladding and Oil bound Distemper Floors: Combination of Natural Stone & tiles Doors: Stainless Steel finished lift doors Ceilings: Oil Bound Distemper Paint Air-conditioned Ground Floor Lobby

# External Façade

Walls: Combination of stone and durable paint

### Servant/Utility Room

Walls: Oil bound distemper
Floors: Ceramic Vitrified tiles
Doors: Hard Wood Door Frame with Flush Shutter
Windows: UPVC/ Powder coated or Anodized Aluminium Glazing
Ceilings: Oil Bound Distemper Paint

## Balcony/Utility Balcony

Floors: Anti-skid/Non-slippery ceramic/vitrified tiles

## Staircases

Walls: Oil Bound Distemper Paint Floors: Kota in tread and risers or exposed RCC Doors: Steel fire doors/fire resistant shutter Ceilings: Oil Bound Distemper Paint

# **Electrical Equippments**

Ceiling fans & Light fittings Split AC in Bedrooms and Living & Dining Geyser in Masterbed Toilet