M3M Sierra Specification:

Walls	1	Plastic Emulsion with Roller Finish		
Floors		Kota Stone/ Tiles/ Exposed RCC		
Doors		Hard Wood Door Frame with Flush Shutter		
Windows	1	UPVC/Powder coated or Anodized Aluminium Glazing		
Ceiling	1	Plastic Emulsion		
Living	g /]	Dining Room		
Walls		Plastic Emulsion with Roller Finish		
Floors		Vitrified Tiles		
Doors		Hard Wood Door Frame with Flush Shutter		
Windows	1	UPVC/Powder coated or Anodized Aluminium Glazing		
Ceiling	1	Plastic Emulsion		
Kitch Walls	en	50.8 mm (2 inch) high ceramic tiles above counter, balance OBD paint		
Floors		Anti skid ceramic tiles		
Doors	I	Hard Wood door framewith flush shutter		
Windows	I	UPVC/Powder coated or Anodized Aluminium Glazing		
Ceiling		Oil Bound Distemper Paint		
Cennig		Polished Granite counter with SS sink and CP fittings		

Walls		Combination of Ceramic Tiles, Oil Bound Distemper & Mirror
Floors		Anti skid Ceramic tiles
Doors	I	Hard Wood Door Frame with Flush Shutter
Windows	I	UPVC/Powder coated or Anodized Aluminium Glazing
Ceiling	I	Oil Bound Distemper Paint
Other	I	Granite Marble Counter with White Sanitary fixtures and CP fitings
Lift L Walls	ODL	Selected stone/ Tile cladding and Oil bound Distemper
Floors		Combination of Natural Stone & tiles
Doors		Stainless Steel finished lift doors
Ceilings	, 	Oil Bound Distemper Paint
Air		Conditioned Ground Floor Lobby
		Facada
Exter	nal	T'acauc
Exter Walls	nal	Combination of glazing's and exterior paint
Walls		
Walls Dome		Combination of glazing's and exterior paint
Walls Dome Walls		Combination of glazing's and exterior paint 2/Utility Room
Walls Walls Floors		Combination of glazing's and exterior paint 2/Utility Room Oil bound distemper
Walls		Combination of glazing's and exterior paint LUtility Room Oil bound distemper Ceramic / Vitrified tiles

Balcony/Utility Balcony						
Floors	Anti	Anti-skid/Non-slippery ceramic/vitrified tiles				
Staircases						
Walls	I	Oil Bound Distemper Paint				
Floors	1	Kota Stone/ Tiles/ Exposed RCC				
Doors	1	Steel fire doors/fire resistant shutter				
Ceilings	1	Oil Bound Distemper Paint				